

**EMS-A Problem:** The left speaker doesn't seem to be sending any information.

**Solution:** The O2R seems to revert to a bizarre setting on power up. To fix the no left speaker stupidity, the user needs to select the stereo bus (button above on), then go to the panning section and pan it to the center. I don't know why it is doing this, but it is a very easy fix.

- chris